

Part Description	Part Number
Complete Parts List	Form 12-26
Balancer accessories	Form 3203T
USB Program and Data Drives (For RFE, SWHN, and SWP)	20-3890-1
Air regulator	136-78-2
Belt	126-48-2
Outer Dataset Lateral Hall Effect Sensor	125-415-3
Outer Dataset Radial Hall Effect Sensor	125-394-3
Inner Dataset Hall Effect Sensor	125-445-3
DC motor (Motor Brush and Spring 129-245-2. 2 per motor.)	129-238-1
DC motor drive	232-342-2
DC motor pulley	107-112-2
DAQ board (With electronic key holder)	45-1679-1
DAQ board (For SpeedClamp. Software 6.1 or higher required) Was 45-1679-1. Now 45-1835-1 and cable kit 37-819-1.	20-3974-1
Force transducer	109-182-1
Hood switch (with harness)	18-497-1
Motherboard	See this FAQ
Power switch (on balancer neck)	18-565-2
Power switch outer housing	105-639-2
Power switch inner housing	105-640-2
Power supply (150 watt)	232-373-2
Spindle encoder board (replaces 45-1159-1)	45-1913-1
Spindle encoder cable	38-837-1
Switch – spindle lock	18-454-2
Monitor	227-05-2
Spindle laser	105-493-1
Standard wingnut bearing and washer kit	130-250-3
Thread Repair Kit for 76-574-2 Pro Grip Quick Nut	20-3417-2
Handle Repair Kit for 76-574-2 Pro Grip Quick Nut	20-3519-2
Repair Kit for 76-438-2 Pro Grip Quick Nut	20-2137-2

76-438-2



76-574-2

