

Description	Part Number
V Drive Belt	126-51-2
DAQ Board Was 45-1597-1 OR 45-1697-1. Now 45-1835-1 and cable kit 37-819-1.	20-3972-1
Power supply (150 watt) Serial numbers GE and higher	232-373-2
Power supply (150 watt) Serial numbers FE and lower	20-3744-1
DC Motor Drive	232-323-2
DC Drive Relay (2 Used)	18-571-2
HammerHead LED Light Strip	35-176-2
User Interface Return Switch Overlay	18-611-2
User Interface Board / Rotary Knob (Replaces 45-1639-1)	45-1743-1-1
Power Filter	136-93-2
Main Board With RAM (Replaces 45-1545-2)	45-1657-2
Outer Camera / Laser	125-517-1
Inner Camera / Laser	125-516-1
Cable, inner camera	38-1312-1
Cable outer camera	38-1313-1
Hood Rotation Sensor	125-518-1
Foot Pedal Reed Switch (Magnetic Actuator – 60-24-2)	18-615-1
Wingnut Bearing	130-186-2
Repair Kit for 76-574-2 Pro Grip Quick Nut	20-3417-2
Handle Repair Kit for 76-574-2 Pro Grip Quick Nut	20-3519-2
If replacing the Intel mother board with the Advantech mother board order 20-2895-1	
22 Inch LCD	227-106-2
Power Switch with LED (on side of monitor support)	18-565-2
Spindle Housing Assembly (Replaces 105-740-1)	105-790-1
Spindle Outer Shaft (Replaces original 97-683-2)	97-727-2
Force Transducers	109-182-1
Spindle Encoder Board (replaces 45-1159-1)	45-1913-1
USB Program and Data Drives	20-3890-1

76-574-2